

# Download Fault Codes For Prostar International

INTERNATIONAL Navistar Truck Operator, Service Manuals PDF & Wiring Diagrams download free - 4700, CF500, CF600, NS, Prostar, DuraStar, WorkStar, TerraStar, PayStar ...2019 INTERNATIONAL PROSTAR Recall - SEAT BELTS:FRONT:ANCHORAGE Problem: Navistar, Inc. (Navistar) is recalling certain 2018-2019 International WorkStar, DuraStar, LoneStar, LT, ProStar, RH and IC Bus HC, 2018 International TranStar, 2019 International HV and MV trucks and transit buses.9999 CUMMINS ISX15 Recalls (5) Campaign: 11E031000 on 08/08/2011 Component: Engine and engine cooling Affected: 11,860 Defect: Cummins is recalling certain isb6.7, isc8.3, isl9, isx11.9, and isx15 engines shipped from september 2010 through december 2010 to various vehicle manufacturers.9999 INTERNATIONAL HARVESTER INTERNATIONAL TSBs (543) Bulletin: 971001G97904 Component: 162810 structure:body:hood:hinge and attachments Summary: Procedures on installation of center mount hood hinge kits.