

Download York Millenium Recip Chiller Manual

108 YORK INTERNATIONAL Micropanel CHILLER CONTROL PANEL PROGRAMMING AND DATA ACCESS DISPLAY AND STATUS INFORMATION KEYS Status Key - see Section 2 This key provides a display of the current operationalFORM 150.60-NM5 YORK INTERNATIONAL 3 UNIT NOMENCLATURE Compressor Series Compressor Style (G or K) No. of Active Cylinders (4) Stroke (3, 4) Steps of UnloadingYORK Millenium Recip chiller Hi guys My problem with this york controller is that the low pressure alarm is set to 3,31bar and the water temperature required (set point) is 5 C (R407c).This is a 1997 York millennium screw chiller. I had to make repairs to the eductor block and lines also replace filters. The unit was pumped down to the condenser barrel.